

VIBRATION MEASUREMENT PITFALLS PROJECT KKU52450 at Energiforsk

Åsa Collet and Jessica Fromell 2021-11-10







Åsa


Krister

About Efterklang[®]

Jessica

We have provided advice on acoustics, noise and vibration control since 1956 when Ingemansson Technology was founded in Sweden. In 2006 AFRY acquired Ingemansson and today Efterklang is a leading acoustic consultancy.

We are represented in Denmark, Norway, Sweden and Switzerland. Our team consists of 130+ dedicated acousticians and sound designers.



efterklang: PART OF AFRY

Objective

The objective is to assemble knowledge and experience in the area of vibration measurement pitfalls.

Summarized experience are collected by interviews from the Nordic nuclear power plants together with Efterklang's own experiences within the field.

The assembled information can be used to increase awareness of which pitfalls one might encounter doing vibration measurements and how to best avoid them when working with maintenance and quality assurance in a LTO perspective

VIBRATION MEASUREMENT PITFALLS


REPORT 2021:803





Content

- 1. Questionnaire Interviews
- NPP Vibration measurement pitfalls – Some shared experience in short
- 3. Examples of 5 pitfalls
- 4. Summary





3. NPP Vibration Measurement Pitfalls

Questionnaire

- 1. Measure response vibrations on a machine/pipe/foundation etc.
- 2. Measure reference signals (s) from force input.
- 3. Preparation of measurements
- 4. Validation of measurement chain Transducers
- 5. Validation of measurement chain Signal
- 6. Validation of measurement chain Connections and cables between transducers
- Validation of measurement chain Frontend and intermediate boxes
- 8. Validation of measurement chain Applied software and firmware
- 9. Validation of measurement chain Book keeping
- 10. Selection of measurement points
- 11. Validation of results

Interviews

Performed with each NPP via digital meeting

<text><text><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></text></text>	<list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item>
362 Energiforsk	203 Energiforsk
<section-header><section-header><section-header><text><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></text></section-header></section-header></section-header>	<section-header><section-header><section-header><section-header><section-header><section-header><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></section-header></section-header></section-header></section-header></section-header></section-header>

C Energiforsk

3.1 NPP Vibration measurement pitfalls fields - Some shared experiences in short



RINGHALS

OKG


FORSMARK


<u>TVO</u>

FORTUM


- Cables, connectors and sensor pitfalls
- Pitfalls due to inexperience and lack of training of personnel
- · Pitfalls due to selection of measurement positions and insufficient preparation of measurements
- Pitfalls using ICP sensors on steam turbines
- Pitfalls due to communication/documentation mistakes. Eg structural changes of a rebuild/modification affecting not communicated with vibration specialists --> longer investigation time of problem, making wrong conclusions etc.
- Boundary condition issues when doing steam turbine modal measurements. The BC are never the same as during operation.
- Turbine testing with eddy current sensors
- Pitfalls due to lack of bookkeeping/documentation eg. Previous measurement positions, sensors used, levels measured that results in comparison of non-comparative results

EXAMPLE PITFALL 1: TURBINE ROLL-UP WHEN THROTTLED WET STEAM FLOW






• Wet steam excites high frequency tones i.e. above f=10 kHz.




7

efterklang: | PART OF AFRY

EXAMPLE PITFALL 2: LOW-FREQUENCY SKI-SLOPE







Laser Doppler Vibrometer, LDV Accelerometer ICP

- Transients from the pump
- The vibration must be "quicker" than the relaxation of the signal.



Example Pitfall 3: Unexpected phase shift from peripherical devices measuring current I and voltage V



AmpFlex current sensors

After a complementary verification of the current sensor, the phase shift ended up to be 24° @ 2.4 A instead of the specified at data sheet 20° @ 10 A at f=50 Hz.




Analog isolation amplifier used to transform voltage 110.0 V on terminal to 5.47 V range suitable for measurement system

Upon phase verification it was verified that each input module of the isolator amplifier add a phase shift of approximately 17° @ 50 Hz during the prevailing circumstances



Example Pitfall 4: Unexpected amplitude of motor component







- All components were aligned to meet at least 0.05 mm parallelism and 0.05 mm/100 mm in angle alignments.
- Use of self-adjusting Vibracon foot for angle error
- Grease in cup holder

Example Pitfall 5: Missed and non-synchronized project information



Design of new pump foundation.

- Lack of communication between project experts pipe engineers and foundation design engineer.
- Missed the dynamic influence of strong constraints had on the discharge and suction pipes to the pump



Summary

- When you work in a group ٠ with a mixture of different project disciplines, suppliers and/or change of instrumentation nothing should be taken for granted.
- Often a tight timetable and/or ٠ lack of resources requires a longer and extensive preinvestigation before project start-up to achieve reliable measurement information when the project is running.

Found fault	Possible pitfall 1	Possible pitfall 2	Possible pifall 3	Possible pifall 4	Possible pifall 5	Possible pifall 6	Possible pifall 7
Unexpected DC component/ski- slope	ICP accelerometer, section 3.1.5- 3.1.6	High frequency overload, section 3.2.2	Steam pipe meas urement Section 5.1 and 2.3	Section 2.1.2, 2.3. Eg. Faulty cables, wrong sensors, temperature and radiation sensitivity	Integration issues section 2.4 and 3.1.5		
Unexpected 50 Hz component or other disturbances	Impact testing, section 3.1.4	Interfering potent ials, Section 5.2	2.2 impact testing during parallel work	2.3 and 5.2 Grounding issues. Transients due to cabling section 2.3	Not galvanically sepa rated channels section 2.6		
Unexpected vibration magnitude/ frequency	Sensor malfunctioning, section 3.2.1	Selection of measurement points, Section 4.3	Inconsistent alignment, Section 4.4	Section 2.1 Standards and Vibration criteria's, alarm levels	Section 2.1.1 Fixture points and resonances of fixtures	2.1.1 and 2.3 using filters and amplifiers. And attachment of sensors	Sensor sensitivity, section 2.3
Unexpected phase shift	Disturbance of high frequency vibration, section 5.1	Amplifiers, section 6.2 and 2. 3 and 2.6	Operating over long cables (> 30m) with ICP sensors, Section 6.3	Bookkeeping and selection of points sections 2.8 and 2.9			
Missing project information	No rotor-dynamic model available, section 4.2	Preparation, se ction 7.1, Section 2.1.2	Section 2.1.1 and 2.1.2 Unable to access before or during meas.	Underestimation of construction changes Section 2.1.2	Bookkeeping section 2.8		
Malfunctioning Equipment or poor signal quality	Sensitivity to radiation sectio n 2.1.1 and 2.3 and 6.3	Using wrong Filters and sensors, eg se ction 2.3	Poor/wrong attachment section 2.3	Cabling and connection, section 2.3			
Something breaks but root cause is hard to find.	Section 2.1.1 Not enough measurement time to find actual						



Thank you!

