



#### June 2019:

Successful 12Km tunnel inspection at Duge pumping station

#### Background













Project Engineer	Project Manager	Technical Support Manager
Technical Manager	Asset Manager	General Manager
Diving Supervisor	ROV Supervisor	ROV Pilots













Work Class ROV Systems


Resident Remote Controlled Systems





NEXXUS

## Design Criteria – Development of tunnel Survey ROV



Range	Dimensions	Infrastructure
15 000 m	Light weight	Battery powered
	Small dimensions	





5











## Product

#### **NOTUS ROV**

ROV70Controlroom70Battery20Fibercable15

700Kg 700Kg 20Kwh 15Km



# Saurdal

**Purpose:** Verification of known rockslide

**Conclusion:** Rockslide identified 1300m from shafthouse.

**Time-consume:** 4 h in tunnel- 24 h mob/demob








## Duge


**Purpose:** Inspection of sandtraps and potential rockslide


Conclusion: No major irregularities found


**Time-consume** 14 h in tunnel- 48 h mob/demob












### Data

**360 Degrees Sonar-Live & post porcess** 

**Profiling Sonar** 

**Postion Data** 

Visual/Video



#### Open Platform – Technology & Competence conversions from O&G subsea

